

## LISTA VIN / CAMPAÑAS DE SEGURIDAD

Item	Pais	Marca	Tipo Campaña	ID campaña	Descripción Campaña	VIN	Año Modelo
1	Colombia	LANDROVER	RECALL	N124	VIRTUAL INSTRUMENT CLUSTER GOING BLANK	SALWA2FV3HA677709	2017
2	Colombia	LANDROVER	RECALL	N124	VIRTUAL INSTRUMENT CLUSTER GOING BLANK	SALWA2FK6HA135932	2017
3	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BX9JH321510	2018
4	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA5BX6JH323779	2018
5	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BX7JH322798	2018
6	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG1HH200173	2017
7	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG3HH229769	2017
8	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG7HH261933	2017
9	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG1HH215269	2017
10	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG0HH202030	2017
11	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG4HH239145	2017
12	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG3HH215208	2017
13	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA5BGXHH213067	2017
14	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BGXHH200303	2017
15	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG8HH200980	2017
16	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG8HH215124	2017
17	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG1HH202036	2017
18	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG2HH210548	2017
19	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG7HH184304	2017
20	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG9HH191738	2017
21	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG1HH191703	2017
22	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG8HH193366	2017
23	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG9HH181601	2017
24	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG8HH191682	2017
25	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG7HH191673	2017
26	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BGXHH191750	2017

27	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG9GH086776	2016
28	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG5GH083390	2016
29	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG8GH082007	2016
30	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG6GH081938	2016
31	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG7GH081852	2016
32	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG0GH081854	2016
33	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG6GH086721	2016
34	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG0GH081949	2016
35	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG1GH082009	2016
36	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG6GH086718	2016
37	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG5GH086709	2016
38	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG0GH082003	2016
39	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG6GH081941	2016
40	Colombia	LANDROVER	RECALL	N291	ENGINE SYSTEM UPGRADE	SALVA2BG2GH082052	2016
41	Colombia	LANDROVER	RECALL	N341	WASHER JET PUMP FUSE	SALZA2BX9LH016240	2020
42	Colombia	LANDROVER	RECALL	N341	WASHER JET PUMP FUSE	SALZA2BX8LH017153	2020
43	Colombia	LANDROVER	RECALL	N568	FRONT ROW RIGHT SEATBELT	SALZA2BX8MH139061	2021
44	Colombia	LANDROVER	RECALL	N568	FRONT ROW RIGHT SEATBELT	SALZA2BX1MH140665	2021
45	Colombia	LANDROVER	RECALL	P080	CRANK POSITION SENSOR SIGNAL ISSUE	SALLSAAF4DA769649	2013
46	Colombia	LANDROVER	RECALL	P080	CRANK POSITION SENSOR SIGNAL ISSUE	SALLAAAF4CA628794	2012
47	Colombia	LANDROVER	RECALL	P080	CRANK POSITION SENSOR SIGNAL ISSUE	SALLSAAF4DA773410	2013
48	Colombia	LANDROVER	RECALL	P080	CRANK POSITION SENSOR SIGNAL ISSUE	SALLSAAF4DA777971	2013
49	Colombia	LANDROVER	RECALL	P080	CRANK POSITION SENSOR SIGNAL ISSUE	SALLSAAF4DA778283	2013
50	Colombia	LANDROVER	RECALL	P080	CRANK POSITION SENSOR SIGNAL ISSUE	SALLAAAF4CA626815	2012
51	Colombia	LANDROVER	RECALL	P095	AUTOLIV SEATBELT OPERATION	SALCA2BG0HH646239	2017
52	Colombia	LANDROVER	RECALL	P095	AUTOLIV SEATBELT OPERATION	SALWA2FF0GA122529	2016
53	Colombia	LANDROVER	RECALL	P095	AUTOLIV SEATBELT OPERATION	SALWA2VF7GA116888	2016
54	Colombia	LANDROVER	RECALL	P095	AUTOLIV SEATBELT OPERATION	SALCA2BG0HH640067	2017